

















LINTEL SHEET 1 - LAST REVISION 3/17/21




882 N. Marshall Way
 Layton, UT 84041
 Ph. (801) 544-9054
 Fax: (801) 544-9154




LINTEL SHEET 2 - LAST REVISION 3/17/21




882 N. Marshall Way
Layton, UT 84041
Ph. (801) 544-9054
Fax: (801) 544-9154




L7-8
1 @ 48"




L8-1
8 @ 48"




L8-2
2 @ 48"
1 @ 96"




L8-3
1 @ 96"




L8-4
2 @ 96"




L8-5
3 @ 96
5 @ 48"




L8-6
2 @ 96"




L8-7
1 @ 48"




L8-8
2 @ 95.375" w/finends,
1 12" x 12" corner w/finends




L8-9
2 @ 47.625"
1 leftfinend
1 rightfinend




L8-10
2 @ 72"
2 @ 120"




L8-11
2 @ 96"




L8-12
2 @ 96"




L8-13
1 @ 96"



L8-14
2 @ 96"
2 steel blkhds



L8-15
3 @ 96"




L8-17
3 @ 96"


LINTEL SHEET 3 - LAST REVISION 3/17/21




882 N. Marshall Way
Layton, UT 84041
Ph. (801) 544-9054
Fax: (801) 544-9154




L9-1
4 @ 64"




L9-2
3 @ 72"




L9-3
4 @ 96"




L9-4
1 @ 36"




L9-5
1 @ 48"




L10-1 Arch
1 @ 56"




L10-2
5 @ 96.0
6 steel bulkheads




L10-3
2 @ 96"



L11-1
1 @ 48"



L11-2
3 @ 48"
5 @ 50 double finend




L12-1
2 @ 48"


LINTEL SHEET 4 - LAST REVISION 3/17/21




882 N. Marshall Way
Layton, UT 84041
Ph. (801) 544-9054
Fax: (801) 544-9154



L12-4
2 at 96 chamfer ends



L12-5
3 at 96"
Monache




L12-6
1left 1right 50.375 flat
1left 1right 50.375 vert
quarry bend


LINTEL SHEET 5 - LAST REVISION 3/17/21




882 N. Marshall Way
Layton, UT 84041
Ph. (801) 544-9054
Fax: (801) 544-9154



L13-1
1@48"



L14-1
2 left 50.375
2 right 50.375
central district phase II




L16-2
2 at 96 chamfer ends


LINTEL SHEET 6 - LAST REVISION 3/17/21




882 N. Marshall Way
Layton, UT 84041
Ph. (801) 544-9054
Fax: (801) 544-9154




L18-1
1left44
1right44
1 flatleft 44
1 flatright44
4heads
Quarry Bend



L24-1
1 @ 48"



L24-2
5 at 48" double corner
2 at 48" Straight
Lowe's Show Low Az



L48-1
2 at 60 double corner
1 at 60 Straight
Lowe's Show Low Arizona